Wednesday, 1/31/2007 2:59:23 PM Kim Johnston User **Process Sheet** : ARM Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 30539 **Estimate Number** : 12590 : D35604~ : N/A Part Number P.O. Number : D3560 UNDER REVIEW S.O. No. : N/A : 1/31/2007 **Drawing Number** This Issue : NC : N/A Prsht Rev. Project Number : NIA-: SMALL /MED FAB Type First Issue **Drawing Revision** : 29450 Material **Previous Run** : 2/7/2007 Due Date Written By Checked & Approved By UNew Issue 06-11-10 JLM : Est Rev:A Comment **Additional Product** Job Number: Description: Seq. #: 6061-T6 Bar .50" x 6.0" M6061T6B0500X06000 1.0 Comment: Qty.: Total: 1 f(s) 6061-T6 Bar .50" x 6.0" Batch: M 103435 2.0 WATER JE Comment: FLOW WATER JET 1-Cut as per Dwg D3560 M 07 02 13 Prog Rev: A 2-Deburr if necessary Note: 507" Dia & .196" Dia Holes are to opened on manual mill after Waterjet INSPECT PARTS AS THEY COME OFF MACHINE 3.0 QC2 0702 14 Comment: INSPECT PARTS AS THEY COME OFF MACHINE CONVENTIONAL MILLING MACHINE 4.0 MILLING CONV DIP07/02/17 (4) Comment: CONVENTIONAL MILLING MACHINE 1-Open .196" Dia hole 2-C'Bore as per Dwg D3560. 3-Ream .507" as per Dwg D3560 \*\*\*Ensure to C'Bore on Corect side\*\*\*

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGE					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		*				ī	
Part No	:	PAR #: Fault Category:	NCR: Yes	(No) DO		Date: C	7/12/21

QA: N/C Closed: \_\_\_\_ Date: \_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section	n B	Verification	Annroval	Ammental		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto		
					j					
		•						:		
				G.		<u> </u>				
							1			
				c ŝ			t			
							i			

NOTE: Date & initial all entries

Wednesday, 1/31/2007 2:59:24 PM Dąte: User: 1 Kim Johnston **Process Sheet** Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Job Number: 30539 Part Number: D35604 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 6.0 4 Comment: SECOND CHECK PACKAGING 1 PACKAGING RESOURCE #1 7.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 57 8.0 QC21 Comment: FINAL IN SPECTION/W/O RELEASE V 52024 Job Completion 


## **Dart Aerospace Ltd**


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						÷	
						, i	•

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Administrati	Ammoval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
						,				
		4)								
•										
							t .			
					·					
			4				ļ			

NOTE: Date & initial all entries





DART AEROSPACE LTD	Work Order:	30539
	Part Number:	D3560-4
Description: ARM  Inspection Dwg: N35/c/ Rev: A		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	X	Prototype
X	First Article	X	Prototyp

Drawing Dimension	Tolerance	Actual Dimension	Accept	lèjest	Method of Inspection	Comments
0.500	+1-0.010	0.502	1		vern	
1.750	41-0.010	1.750	V		vern	
2.465	+1-0.010	2.470	1		Norn	
0.135	41-0.010	0.130	1		vern	
0.250	+1-0.010	0.252	$\sqrt{}$		VlrN	
1.702	H-0.010	1.706	V		very	
3,000	+1-0.010	2.003	1		VerN	
0.196	+0.005/-0.001	0.197				
0.5.7	+0.000/-0.001	0.507		,	1.	
0.385 x 100°	+ 0.019 +1/20	0.380 x 100°			9	
0.250	+0,010	0.250				
						,
					,	
			<del>  .</del>			

	DSP07/02/17				
Measured by:	M M	Audited by:	gul	Prototype Approval:	
	7// (3//)	Date:	22/2/2	Date:	
Date:	070619	Date.	0710211 F		

				Revised by	Approved
Re	Date	Change		1011000	
Ke	Date	Change	K	<j jlm<="" th=""><th>1</th></j>	1
^		New Issue	1.5	TOTOLINI	
1 A	1	146 AA 13306			